

Inspection Photos  
Operator: Morningstar  
API: 007-06185  
Date: 1/11/2022



Photo 1. View of project area from the northeastern corner facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation appears to be progressing with mixed wheatgrass such as intermediate wheatgrass and western wheatgrass.





Photo 3. View of the northern project area from the northwestern corner facing eastward.





Photo 4. View of kochia debris within tan battery berms. Kochia debris observed throughout the project area and needs to be removed.





Photo 5. View of kochia debris around the wellhead.





Photo 6. View of reference area, comprised of irrigated crop field, grasses are mowed and appear to be comprised of mixed wheatgrasses.