

Inspection Photos
Operator: Morningstar
API: 007-06212
Date: 1/11/2022



Photo 1. View of project area from the southwestern corner facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation appears to be progressing with mixed wheatgrass such as intermediate wheatgrass and western wheatgrass. Unused equipment stored within the southern project area. Interim reclamation needs to be conducted within areas not needed for production operations.



Photo 3. View of the northern project area from the northwestern corner facing eastward.



Photo 4. View of reference area, comprised of irrigated crop field, grasses are mowed and appear to be comprised of mixed wheatgrasses.