

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/12/2022

Submitted Date:

01/14/2022

Document Number:

690202489

FIELD INSPECTION FORM

Loc ID 324789 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 95620
 Name of Operator: WESTERN OPERATING COMPANY
 Address: 1165 DELAWARE STREET #200
 City: DENVER State: CO Zip: 80204

Findings:

- 4 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Hart, Dale		dale@westernoperating.com	
JAMES STEVEN D		steve@westernoperating.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
150024	UIC DISPOSAL	AC	09/08/1969		-	SALT WATER DISPOSAL 1	RI
212608	WELL	IJ	09/06/2018	DSPW	061-05061	WEAR 1	RI

General Comment:

[This is a location Inspection.](#)
[See attached photos and additional details within this report.](#)

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:			
Corrective Action:			Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	There is weed debris along the fence that needs to be removed.		
Corrective Action:	Comply with 606.		Date: 01/21/2022

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:

Type	LOCATION		
Comment:	The electric fence around the location is not maintained to prevent livestock entry.		
Corrective Action:	Comply with the fencing requirements per the 1002a rules		Date: 01/21/2022

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	4	500 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition			
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Insufficient		
Comment:	There is animal burrows compromising the berm around the tank battery. The secondary containment is not sufficiently impervious to contain spill. Earthen berms need to repaired and compacted.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 912.d.(1).			Date: 02/04/2022

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690202490	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5634392