

FORM  
INSPRev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/10/2022

Submitted Date:

01/10/2022

Document Number:

699304767

### FIELD INSPECTION FORM

Loc ID 318526 Inspector Name: Revas, Robbie On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**17 Number of Comments1 Number of Corrective Actions

- 
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241494	WELL	SI	10/01/2021	OW	123-09283	CHAMPLIN 525 AMOCO "A" 1	SI

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	SEPARATOR		
Comment:	barb wire		
Corrective Action:		Date:	
Type	OTHER		
Comment:	pig station has fabricated square tubing		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Ag panel		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	hog fence		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Ag panel		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	barb wire		

Corrective Action:		Date:	
<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 3		
Comment:	automation		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Card in meter house indicates that calibration is not current		
Corrective Action:	Provide calibration records or calibrate meter as required by Rule 430 within 30 days. Proof of calibration may be provided on a Field Inspection Resolution Report (FIRR).		Date: 02/10/2022
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	gas engine		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	FIBERGLASS AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment: <b>Shares containment with crude tank</b>							
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	1	300 BBLs	STEEL AST		40.162770,-104.466610		
Comment:							
Corrective Action:						Date:	

**Paint**

Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:							
Corrective Action:						Date:	

**Wells Served By Facilities Above**

**AirsID**

API Number	API Number	AirsID
123-09283		

**Venting:**

Yes/No	NO						
Comment:							
Corrective Action:						Date:	

**Flaring:**

Type							
Comment:							
Corrective Action:						Date:	

**Inspected Facilities**

Facility ID: 241494 Type: WELL API Number: 123-09283 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 09/22/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On Monday 1/10/2022 at approximately 1423 hrs. I, Inspector Robbie Revas,                      Conducted an on-site inspection:                      Operator: Chevron/Noble                      Location: Champlin 525 Amoco A #1</p> <p align="center">API # 05-123-09283</p> <p align="right">County: Weld</p> <p>While there, I observed a well site and tank battery, SI at the time of inspection.                      During this inspection the following possible compliance issues were observed:                      430 Calibration: Meter not calibrated annually, CA date 2-10-2022.                      See attached photos.                      Location: snow covered, Weather: clear.                      A follow up on this site inspection needs to be conducted to ensure the                      Compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	revasr	01/10/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402922289	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5629381">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5629381</a>
699304768	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5629377">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5629377</a>