

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/13/2022

Submitted Date:

01/17/2022

Document Number:

701102508

FIELD INSPECTION FORMLoc ID: 312507 Inspector Name: LONGWORTH, MIKE On-Site Inspection: ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 53255

Name of Operator: MARALEX RESOURCES INC

Address: P O BOX 338

City: IGNACIO State: CO Zip: 81137

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hahn, Travis		thahn@maralexinc.com	All Inspections
Graves, Jim	970-712-0099	mrinc20@maralexinc.com	Operations Manager
, Engineering		dnr_cogccengineering@state.co.us	All engineering

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221808	WELL	TA	01/01/2021	GW	077-08410	FEDERAL 25-3	WK

General Comment:

Witness Plug and Abandon
 Contactors
 Cross County Well Service
 Rocky Mountain Wireline Service
 Blac Frac
 On location 720 am
 Run in wireline tag plug @ 1485' Set CIBP @ 1300'
 Braden psi 26 psi
 Run tubing in hole to circulate and pressure test casing
 Circulated hole Tested casing to 590 psi for 15 min
 Pumped 8 sacks (93') on top of CBIP
 Run in wireline shoot 4 holes @ 450' collar @ 462'
 Run tubing in hole break circulation down 4½" casing and out 8" surface casing valve
 Pump 55 sacks 15.5lb 450' – 274'

Location**Lease Road:**

Type	Access		
comment:	Rough		
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	DRILLING/RECOMP		
Comment:	Rig signs at intersections		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Good Housekeeping:

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Bradenhead	# 1		corrective date
Comment:	26 psi		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 221808 Type: WELL API Number: 077-08410 Status: TA Insp. Status: WK**Cement**Cement ContractorContractor Name: Blac Frac

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging OperationsDepth Plugs(feet range): 274-400Cement Volume (sx): 55Good Return During Job: YESCement Type: BComment: _____

Corrective Action: _____

Date: _____

WorkoverComment:

Cross County Well Service
 Rocky Mountain Wireline Service
 Blac Frac
 On location 720 am
 Run in wireline tag plug @ 1485' Set CIBP @ 1300'
 Braden psi 26 psi
 Run tubing in hole to circulate and pressure test casing
 Circulated hole Tested casing to 590 psi for 15 min
 Pumped 8 sacks (93') on top of CBIP
 Run in wireline shoot 4 holes @ 450' collar @ 462'
 Run tubing in hole break circulation down 4½" casing and out 8" surface casing valve
 Pump 55 sacks 15.5lb 450' – 274'

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701102509	Inspection 701102508 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5635690