

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

| Type | Area | Volume | | corrective date |
|-----------------------------------|------|--------|--|-----------------|
| Type: Plunger Lift | | # 0 | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Type: Gas Meter Run | | # 0 | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Type: Bradenhead | | # 0 | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Type: Emission Control Device | | # 0 | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Type: Ancillary equipment | | # 0 | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Type: Vertical Separator | | # 0 | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Type: Horizontal Heated Separator | | # 0 | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|--|-------|
| Yes/No | | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|------|--|
| Type | |
|------|--|

| | |
|--------------------|-------|
| Comment: | |
| Corrective Action: | Date: |

Inspected Facilities

Facility ID: 281548 Type: WELL API Number: 123-23411 Status: PA Insp. Status: PA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: PA, Form 06 (S) Doc # 402209711 plug date 9-20-2019

Corrective Action: _____ Date: _____

COGCC Comments

| Comment | User | Date |
|--|--------|------------|
| <p>COGCC Inspection Report Summary On Tuesday 1/18/2022 at approximately 1215 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Operator: Oxy/Kerr McGee Location: McDonald 12-25 API #: 05-123-23411</p> <p style="text-align: center;">County: Weld</p> <p>While there, I observed a PA wellsite, Form 06 (S) Doc # 402209711 plug date 9-20-2019. During this inspection no compliance issues were observed: See attached photos. Location: Snow covered, Weather: cloudy. No follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p> | revasr | 01/18/2022 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------|---|
| 699304812 | location pics | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5637746 |