

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/11/2022

Submitted Date:

01/12/2022

Document Number:

700600351

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Kosola, Jason On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10705
Name of Operator: EVERGREEN NATURAL RESOURCES LLC
Address: 1875 LAWRENCE ST STE 1150
City: DENVER State: CO Zip: 80202

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Foutz, Paul		paul.foutz@state.co.us	Southeast Aquatics - Arkansas River Basin
Inspections, Evergreen		cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
481394	SPILL OR RELEASE	AC	01/12/2022		-	Becks 41-16	EI

General Comment:

This is an environmental inspection to document status of Spill 481394. Any corrective actions from previous inspections that have not been addressed are still applicable. Photos attached to document site condition at the time of inspection. Investigation by operator is ongoing. This inspector observed no impacts to wildlife during inspection. Spill flowed into drainage that is considered Waters of the State. Drainage had no pooled or live water during inspection and only contained snow. Spilled produced water has been absorbed into soil along spill path.

Operator reported:

On January 10, 2022 at 1430, a spill was discovered at the Becks 41-15 well by an employee. The spill originated at the wellhead due to a broken 2" valve on the wellhead water line. The spill was immediately isolated by the employee and additional employees were notified to assess damage/spill volume. Initial estimations of spill volume are 53.4 bbls of produced water. The spill ran south 20 feet from the source at the wellhead, changed direction, flowed 110 feet northeast, entered a culvert, and flowed 60 feet south off location. The spill then flowed 410 feet south where it entered a dry arroyo which has been identified as waters of the state and high priority habitat

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment: Spill of 53.4 bbl of produced water occurred on 1/10/2022. See attached photos of flow path. No standing water from spill was observed during inspection. Produced water from spill that flowed off of the well location was absorbed into the soil. Operator has obtained soil samples from this area.

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 481394 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Less than 2-feet of freeboard

Corrective Action: Lower fluid level so at least two feet of freeboard exists per Rule 909.c.

Date: 01/12/2022

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: _____ Lat: _____ Long: _____

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____

Corrective Action _____

Date: _____

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment: _____

Corrective Action _____

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: _____

Corrective Action _____

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment: _____

Corrective Action _____

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402924096	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5630888
700600352	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5630887