

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/19/2022

Submitted Date:

01/19/2022

Document Number:

699804021

**FIELD INSPECTION FORM**

Loc ID 335060 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

24 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
279996	WELL	PR	05/01/2021	GW	045-11159	PUCKETT/TOSCO PA 542-34	PR
279997	WELL	PR	11/14/2006	GW	045-11158	PUCKETT/TOSCO PA 412-35	PR
279999	WELL	PR	09/13/2005	GW	045-11157	PUCKETT/TOSCO PA 432-34	PR
280001	WELL	PR	09/13/2005	GW	045-11156	PUCKETT/TOSCO PA 532-34	PR
280003	WELL	PR	09/13/2005	GW	045-11155	PUCKETT/TOSCO PA 12-35	PR
280108	WELL	PR	09/19/2005	GW	045-11192	PUCKETT/TOSCO PA 312-35	PR
280109	WELL	PR	07/20/2006	GW	045-11193	PUCKETT/TOSCO PA 442-34	PR
280110	WELL	PR	09/19/2005	GW	045-11194	PUCKETT/TOSCO PA 332-34	PR
280111	WELL	PR	09/19/2005	GW	045-11195	PUCKETT/TOSCO PA 342-34	PR
280112	WELL	PR	09/19/2005	GW	045-11196	PUCKETT/TOSCO PA 42-34	PR

**General Comment:**

COGCC Inspection Report Summary

On Tuesday 1/18/22 at approximately 14:00 hours, I, Inspector Corey De Paolo,  
Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC ARCO-TOSCO-66S95W /34SENE,  
Location #335060 in Garfield County Colorado.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1) Vent pipe on tank open ended with a corrective action date of 1/26/22.

-Location is located in a high priority habitat area.

A follow up on this site inspection needs to be conducted to ensure the  
Compliance issues have been corrected to comply with COGCC rules.  
This is a summary of inspection report.

### Location

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include an attached storage tank. The storage tank is approximately 2'x3'x14' with an approximate capacity of 15 bbl. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tank		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	

<b>Equipment:</b>				corrective date
Type: Gas Meter Run	# 10			
Comment:				
Corrective Action:				Date:
Type: Ancillary equipment	# 1			
Comment:	Chemical tank			
Corrective Action:				Date:
Type: Bradenhead	# 10			
Comment:	No form of pressure monitoring equipment located on braden heads. All braden head valves are accessible.			
Corrective Action:				Date:
Type: Other	# 1			
Comment:	Vent pipe on tank open ended.			
Corrective Action:	Operators will prevent and minimize adverse impacts to wildlife resources.			Date: 01/26/2022
Type: Plunger Lift	# 10			
Comment:	All wells on plunger lift			
Corrective Action:				Date:
Type: Bird Protectors	# 6			
Comment:				
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 10			
Comment:				
Corrective Action:				Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
			Date:	

**Venting:**

Yes/No	NO	
--------	----	--

Inspector Name: De Paolo, Corey

Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	279996	Type:	WELL	API Number:	045-11159	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	279997	Type:	WELL	API Number:	045-11158	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	279999	Type:	WELL	API Number:	045-11157	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	280001	Type:	WELL	API Number:	045-11156	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	280003	Type:	WELL	API Number:	045-11155	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	280108	Type:	WELL	API Number:	045-11192	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	280109	Type:	WELL	API Number:	045-11193	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	280110	Type:	WELL	API Number:	045-11194	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				

Facility ID:	280111	Type:	WELL	API Number:	045-11195	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**

Comment: Producing

Corrective Action:

Date:

Facility ID:	280112	Type:	WELL	API Number:	045-11196	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**

Comment: Producing

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Sediment Traps						
Berms						
Ditches						
		Sediment Traps				
		Ditches				
Compaction						
Gravel						
		Berms				
				Material Handling And Spill Prevention		Chemical tank
		Culverts				
		Gravel				

Comment: [Limited storm water inspection due to location being covered with snow.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<a href="#">Refer to Equipment for corrective actions.</a>	depaoloc	01/19/2022

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699804022	Photos for Insp. #699804021	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5638194">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5638194</a>