

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/19/2022

Submitted Date:

01/19/2022

Document Number:

699804019

FIELD INSPECTION FORMLoc ID 335072 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

14 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
16	WELL	PR	05/16/2006	GW	045-11668	PUCKETT/TOSCO PA 621-35	PR
17	WELL	PR	05/27/2006	GW	045-11669	PUCKETT/TOSCO PA 421-35	PR
18	WELL	PR	05/29/2006	GW	045-11670	PUCKETT/TOSCO PA 521-35	PR
264437	WELL	PR	09/29/2003	GW	045-08218	PUCKETT PA 21-35	PR

General Comment:**COGCC Inspection Report Summary**

On Tuesday 1/18/22 at approximately 13:00 hours, I, Inspector Corey De Paolo, Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC PUCKETT/TOSCO-66S95W /35NENW, Location #335072 in Garfield County Colorado.

Refer to document #699803669 conducted on 9/30/21/ All previous corrective actions have been completed.

While there, I observed normal production operations.

This is a summary of inspection report.

LocationOverall Good: ☒

Signs/Marker:			
Type	OTHER		
Comment:	Separator units include an attached storage tank. The storage tank is approximately 2'x3'x14' with an approximate capacity of 15 bbl. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:			
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 4		
Comment:	No form of pressure monitoring equipment located on braden heads. All braden head valves are accessible.		

Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 4		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Gathering Line	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	16	Type:	WELL	API Number:	045-11668	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	17	Type:	WELL	API Number:	045-11669	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	18	Type:	WELL	API Number:	045-11670	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	264437	Type:	WELL	API Number:	045-08218	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
		Gravel				
		Culverts				
Compaction						
		Ditches				
Ditches						
		Ditches				
		Berms				
Sediment Traps						
Gravel						
Berms						
		Sediment Traps				

Comment: [Limited storm water inspection due to location being covered with snow.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Refer to Sign/Markers and Storm water for comments.	depaoloc	01/19/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699804020	Photos for Insp. #699804019	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5638193