

**Inspection Photos**  
**Location Name: Ignacio Gas Plant**  
**Facility ID: 412668**



**Hydrovac truck on site removing impacted material.**



**Personnel removing impacted material from within secondary containment berm.**

**Inspection Photos**  
**Location Name: Ignacio Gas Plant**  
**Facility ID: 412668**



**400 bbl. AST where spill/release originated.**



**Personnel removing ice from within secondary containment berm.**



**Inspection Photos**  
**Location Name: Ignacio Gas Plant**  
**Facility ID: 412668**



**Compressors within steel building.**



**Secondary containment for lube oil containers.**