

Inspection Photos
Location Name: Mollie Corynne 33-7-2 #2A
API: 05-067-08800



Mollie Corynne 33-7-2 #2A location photo.



Mollie Corynne 33-7-2 #2A equipment overview.

Inspection Photos
Location Name: Mollie Corynne 33-7-2 #2A
API: 05-067-08800



Staining beneath the prime mover on the concrete pad and adjacent soil.



Staining beneath prime mover.

Inspection Photos
Location Name: Mollie Corynne 33-7-2 #2A
API: 05-067-08800



Unused equipment near separator.



Drop out tank for supply gas. Prime mover exhaust ported into drum.