

Inspection Photos
Operator: Simcoe
API: 067-06818
Date: 1/14/2022



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation appears to be progressing in portions with western wheatgrass and sand dropseed.




Photo 3. View of the northwestern fill slope facing down-slope. Little desirable vegetation. Russian knapweed is present.



Photo 4. View of reference area comprised of pinyon and juniper woodland with sagebrush, squirreltail, penstemon, and pricklypear in the understory.