

Inspection Photos
Operator: Simcoe
API: 067-08331
Date: 1/14/2022



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation appears to be progressing in portions with western wheatgrass and sand dropseed.



Photo 3. View of erosional channeling approximately 2ft wide and deep observed within the southern project area. Inset shows area where concentrated stormwater flows off of the southern fill slope.



Photo 4. View of reference area comprised of pinyon and juniper woodland with sagebrush, squirreltail, penstemon, and pricklypear in the understory.