



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |  |
|------|------|--------|--|--|--|
|      |      |        |  |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type PUMP JACK

Comment: 4' barb wire

Corrective Action:

Date:

**Equipment:**

corrective date

Type: Bradenhead # 1

Comment: Plumbed to surface

Corrective Action:

Date:

Type: Pump Jack # 1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment # 1

Comment: Electric equipment

Corrective Action:

Date:

Type: Prime Mover # 1

Comment: Electric motor

Corrective Action:

Date:

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 239696 Type: WELL API Number: 123-07484 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 10/15/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: -- Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: --

Comment:

Corrective Action:  Date: \_\_\_\_\_

**COGCC Comments**

| Comment  | User    | Date       |
|--|---------|------------|
| At time of inspection location appears to be in compliance with COGCC rules.<br>At time of inspection weather conditions were cold, overcast, calm, recent snow. | medinaj | 01/20/2022 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description         | URL   |
|--------------|---------------------|---|
| 699503488    | Inspection pictures | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5640396">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5640396</a> |