

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOE /2-W-27

Location ID: 335233



Photo #5730 from entrance to location.



Photo #5731 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOE /2-W-27

Location ID: 335233



Photo #5733 Unused equipment.



Photo #5732 Vent pipe on tank open ended.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOE /2-W-27

Location ID: 335233



Photo #5734 Location lacks stabilization.



Photo #5735 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOE /2-W-27

Location ID: 335233



Photo #5736 Insufficient tracking BMP at entrance to location.