

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL /PA 543-27

Location ID: 335418



Photo #5737 from entrance to location.



Photo #5738 Vent pipe on tank open ended.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL /PA 543-27

Location ID: 335418



Photo #5740 Location lacks stabilization.



Photo #5741 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL /PA 543-27

Location ID: 335418




Photo #5742 Insufficient tracking BMP at entrance to location.