

Inspection Photos
Operator: Logos
API: 067-08064
Date: 1/19/2022



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation is progressing with blue grama, western wheatgrass, and sand dropseed.



Photo 3. View of dense Russian knapweeds within the western project area. Approximately 500 observed. Scattered spotted knapweeds are also present.



Photo 4. View of the eastern project area from the southeastern corner facing northward.



Photo 5. View of bare soils and erosional channeling (inset), up to 10 inches wide and deep within the southern project area. Bare and eroding soils need stabilization here.



Photo 6. View of reference area comprised of open grass field with smooth brome and western wheatgrass observable.