

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/12/2022

Submitted Date:

01/12/2022

Document Number:

701102506

FIELD INSPECTION FORM

Loc ID: 314990 Inspector Name: LONGWORTH, MIKE On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 74290
Name of Operator: RETAMCO OPERATING INC
Address: PO BOX 790
City: RED LODGE State: MT Zip: 59068

Findings:

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Johnson, Joe	406-446-1568	joejohnson@retamco.com	
Gose, Tom	210-216-0819	tomgose@retamco.com	
Thompson, Bud		BLThomps@BLM.gov	
Glennon, Joe	406-446-1568	joeglennon@retamco.com	

General Comment:

COGCC Follow Up Inspection Report Summary
Follow up to 11/16/2021 inspection # 701102217
Corrected action item(s)

- Battery sign installed at tank battery.
- Produced Water label installed on tank.
- Tank has been repaired.

 During this inspection the following compliance issues were observed:

- Separator units include an attached storage tank. The storage tank is approximately 26" x 33" x 60" with an approximate capacity of Calculated 4.7 BBL. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.

 A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Produced Water label installed on tank.		
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Separator units include an attached storage tank. The storage tank is approximately 26" x 33" x 60" with an approximate capacity of Calculated 4.7 BBL. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:	Identify all hazards associated with equipment.		Date: 04/15/2022
Type	BATTERY		
Comment:	Battery sign installed at tank battery.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	TRASH		
Comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PIT		
Comment:			
Corrective Action:			Date:
Type	TANK BATTERY		

Comment:		
Corrective Action:		Date:

Equipment:	corrective date
Type: Horizontal Heated Separator # 1	
Comment:	
Corrective Action:	Date:
Type: Plunger Lift # 1	
Comment:	
Corrective Action:	Date:
Type: Gas Meter Run # 1	
Comment:	
Corrective Action:	Date:
Type: Bradenhead # 1	
Comment:	
Corrective Action:	Date:
Type: Deadman # & Marked # 4	
Comment:	
Corrective Action:	Date:
Type: Bird Protectors # 1	
Comment:	
Corrective Action:	Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:	Tank has been repaired.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	72 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Compaction						
		Compaction				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Blowdown Lined: NO Pit ID: Lat: Long:

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action Date: _____

Fencing:

Fencing Type: Wildlife Fencing Condition: Adequate

Comment:

Corrective Action Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action Date: _____

Anchor Trench Present: Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective Action Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402928071	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5635692
701102507	Inspection 701102506 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5635689