

Inspection Photos
Location Name: Sheldon R. Sickler 2
Location ID: 317963



Photo 1 WH sign



Photo 2 WH

Inspection Photos
Location Name: Sheldon R. Sickler 2
Location ID: 317963



Photo 3 Pump Jack



Photo 4 ancillary equipment

Inspection Photos
Location Name: Sheldon R. Sickler 2
Location ID: 317963



Photo 5 Location sign, flow line manifold

Photo 6 TB sign

Inspection Photos
Location Name: Sheldon R. Sickler 2
Location ID: 317963



Photo 7 Crude oil tank




Photo 8 PW tank

Inspection Photos
Location Name: Sheldon R. Sickler 2
Location ID: 317963



Photo 9 PW tank appears to be leaking from the access port.

Photo 10 Stained soil by PW tank access port

Inspection Photos
Location Name: Sheldon R. Sickler 2
Location ID: 317963



Photo 11 Stained soil by PW tank access port.



Photo 12 leak on PW tank

Inspection Photos

Location Name: Sheldon R. Sickler 2
Location ID: 317963



Photo 13 Gas Meter Run.




Photo 14 Card in meter house indicates that calibration is not current.

Inspection Photos
Location Name: Sheldon R. Sickler 2
Location ID: 317963



Photo 15 Horiz. Heated Sep.



Photo 16 Lease operator and tanker driver draining tank and looking for possible leaks