

# Inspection Photos

API: 071-09381

Operator: XTO ENERGY INC

Inspection Date: 1/24/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-09381 | Date: 1/24/2021

## Inspection Photos



**Photo 1.** Facing north at the beginning of the access road. The cattleguard has been cleaned out and maintained. There is rock rip/rap installed along the road side and additional roadbase has been spread along the road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09381 | Date: 1/24/2021



## Inspection Photos



**Photo 2.** Facing northwest along the access road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09381 | Date: 1/24/2021



## Inspection Photos



**Photo 3.** There is rock rip/rap placed along the roadside. It appears stormwater erosion is occurring along the side of the rip/rap which will need maintenance.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09381 | Date: 1/24/2021



## Inspection Photos



**Photo 4.** Facing northwest toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09381 | Date: 1/24/2021



## Inspection Photos



**Photo 5.** Facing northwest at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09381 | Date: 1/24/2021



## Inspection Photos



**Photo 6.** Facing back south along the access road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09381 | Date: 1/24/2021