

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/24/2022

Submitted Date:

01/25/2022

Document Number:

700703771

## FIELD INSPECTION FORM

 Loc ID 335270 Inspector Name: Ramsey, Scott On-Site Inspection  2A Doc Num: \_\_\_\_\_
**Operator Information:**
 OGCC Operator Number: 96850  
 Name of Operator: TEP ROCKY MOUNTAIN LLC  
 Address: 1058 COUNTY ROAD 215  
 City: PARACHUTE State: CO Zip: 81635
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments

0 Number of Corrective Actions

Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name | Phone        | Email                              | Comment |
|--------------|--------------|------------------------------------|---------|
| , TEP        | 970-285-9377 | COGCCInspectionReports@terraep.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name                 | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------------------|-------------|
| 211158      | WELL | PR     | 08/23/1995  | GW         | 045-06917 | VASSAR-HEATH RMV 21-28        | PR          |
| 274938      | WELL | PR     | 05/20/2005  | GW         | 045-13444 | WEBSTER HILL/HEATH RWF 532-28 | PR          |
| 455833      | WELL | DG     | 01/19/2019  |            | 045-24000 | NPR 24D-3-596                 | DG          |

**General Comment:****COGCC Inspection Report Summary**

On Monday 1/24/2022 at approximately 1100, I, Inspector Scott Ramsey, conducted a routine inspection at TEP RMV 21-28, at Location # 335270 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad.

Location and access are snow covered at the time of inspection. Location is plowed in a path.

This is a summary of inspection report.

| Location   |                     |        |                 |
|--|---------------------|--------|-----------------|
| <b>Lease Road:</b>                                     |                     |        |                 |
| Type   | Access              |        |                 |
| comment:   | Snow covered/plowed |        |                 |
| Corrective ActionL                                     |                     |        | Date:           |
| Overall Good: <input type="checkbox"/>                 |                     |        |                 |
| <b>Signs/Marker:</b>                                   |                     |        |                 |
| Type   | WELLHEAD            |        |                 |
| Comment:   |                     |        |                 |
| Corrective Action:                                     |                     |        | Date:           |
| Emergency Contact Number:                              |                     |        |                 |
| Comment:   | 911                 |        |                 |
| Corrective Action:                                     |                     |        | Date: _____     |
| <b>Good Housekeeping:</b>                              |                     |        |                 |
| Type   | DEBRIS              |        |                 |
| Comment:   |                     |        |                 |
| Corrective Action:                                     |                     |        | Date:           |
| Overall Good: <input checked="" type="checkbox"/>      |                     |        |                 |
| <b>Spills:</b>   |                     |        |                 |
| Type   | Area                | Volume |                 |
| In Containment: No                                     |                     |        |                 |
| Comment:   |                     |        |                 |
| <input type="checkbox"/> Multiple Spills and Releases? |                     |        |                 |
| <b>Equipment:</b>                                      |                     |        |                 |
| Type: Bradenhead                                       | # 2                 |        | corrective date |
| Comment:   |                     |        |                 |
| Corrective Action:                                     |                     |        | Date:           |
| Type: Plunger Lift                                     | # 2                 |        |                 |
| Comment:   |                     |        |                 |
| Corrective Action:                                     |                     |        | Date:           |
| <b>Venting:</b>  |                     |        |                 |
| Yes/No   | NO                  |        |                 |
| Comment:   |                     |        |                 |
| Corrective Action:                                     |                     |        | Date:           |
| <b>Flaring:</b>  |                     |        |                 |
| Type   |                     |        |                 |
| Comment:   |                     |        |                 |
| Corrective Action:                                     |                     |        | Date:           |

**Inspected Facilities**

Facility ID: 211158 Type: WELL API Number: 045-06917 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing

Corrective Action:

Date:

Facility ID: 274938 Type: WELL API Number: 045-13444 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing

Corrective Action:

Date:

Facility ID: 455833 Type: WELL API Number: 045-24000 Status: DG Insp. Status: DG

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 700703779    | Photo log   | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5644027">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5644027</a> |