

Inspection Photos
Operator: Simcoe
API: 067-08764
Date: 1/24/2022



Photo 1. View of project area from the southwestern corner facing center.



Photo 2. View of the southern project area from the southwestern project area facing eastward. Revegetation is progressing with irrigated grasses such as tall fescue and timothy, largely in a grazed condition.



Photo 3. View of the eastern project area from the southeastern corner facing northward.



Photo 4. View of reference area vegetation comprised of grasses such as irrigated grass field, with timothy, tall fescue, and meadow brome.