

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/13/2022

Submitted Date:

01/19/2022

Document Number:

688801098

**FIELD INSPECTION FORM**Loc ID 306805 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 53255

Name of Operator: MARALEX RESOURCES INC

Address: P O BOX 338

City: IGNACIO State: CO Zip: 81137

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

15 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
	970-563-4000	maralextech@gmail.com	All Inspections
Fischer, Alex		alex.fischer@state.co.us	
O'Hare, Mickey	(970) 563-4000/ (719) 429-3529	amohare@maralexinc.com	All Inspections
Hahn, Travis		thahn@maralexinc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
267561	WELL	PR	08/05/2003	GW	067-08800	MOLLIE CORYNNE 33-7-2 2A	EI

**General Comment:**

On January 13, 2022 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Maralex Resources Inc. Mollie Corynne 33-7-2 #2A. For the most recent field inspection report of this facility, please refer to Document #687905140.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L		Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Sign mounted to fencing around pump jack.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Posted on location sign.		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Rods laying next to separator.		
Corrective Action:	Comply with Rule 606.		Date: 02/02/2022
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
Lube Oil	Pump Jack	<= 1 bbl	
Comment:	The concrete pad for the pump jack and the adjacent soil are stained beneath prime mover.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.		Date: 02/18/2022
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Steel post and wire fencing.		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Gas Meter Run	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:	Operating at the time of this inspection.		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Natural gas powered.		

Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	SW marker is missing.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	PVC valve cover.		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Drop out tank for supply gas within 55 gallon drum.		
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Secondary containment for lube oil container.
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On January 13, 2022 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Maralex Resources Inc. Mollie Corynne 33-7-2 #2A. For the most recent field inspection report of this facility, please refer to Document #687905140. The concrete pad beneath the prime mover and the adjacent soil are stained. The SW rig anchor marker was not observed. Three unused rods are laying near the separator.	hughesjo	01/19/2022

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402931061	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5638698">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5638698</a>
688801099	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5638697">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5638697</a>