

Inspection Photos  
Operator: Simcoe  
API: 067-06181  
Date: 1/24/2022



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the northern project area from the northeastern project area facing westward. Revegetation is progressing with western wheatgrass, smooth brome, and intermediate wheatgrass.






Photo 3. View of areas along the western edge of the working area where concentrated stormwater flows off of the well pad eroding channels that flow directly into an irrigation ditch.



Photo 4. View of reference area comprised of open grass field with western wheatgrass, smooth brome, and scattered sagebrush, dormant at this time.