

Inspection Photos  
Operator: Simcoe  
API: 067-07836  
Date: 1/24/2022



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the western project area from the northwestern project area facing southward. Revegetation is progressing grasses, largely grazed, with western wheatgrass and crested wheatgrass observable.



Photo 3. View of the northern project area from the northwestern corner facing eastward.



Photo 4. View of erosional rilling observed along the western edge of the working area and in the fill slope.



Photo 5. View of pinyon juniper woodland with understory of sagebrush, antelope bitterbrush, prickly pear, James galleta, and mat penstemon.