

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W /11NWNE

Location ID: 334982



Photo #5760 from entrance to location.




Photo #5761 Vent pipe on tank open ended.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W /11NWNE

Location ID: 334982



Photo #5762 Location lacks stabilization.



Photo #5763 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W /11NWNE

Location ID: 334982



Photo #5764 Insufficient tacking BMP at entrance to location.