

Final Reclamation Inspection

December 14th, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 323096

Inspection Document #: 701900287

SESW Section 21 T3N R65W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Frank 1-21C
Location ID: 323096



Photo 1. 2021 aerial imagery of the well pad and tank battery (north is up).
Note: The tank battery has been subdued by a new facility owned by another operator.

Inspection Photos
Location Name: Frank 1-21C
Location ID: 323096



Photo 2. Overview photo of the well pad taken at ground level from the northern edge looking south.

Inspection Photos
Location Name: Frank 1-21C
Location ID: 323096



Photo 3. Photos taken from the middle of the well pad. Left photo facing north and right photo facing east. See description under photo 4.

Inspection Photos
Location Name: Frank 1-21C
Location ID: 323096



Photo 4. Photos taken from the middle of the well pad. Left photo facing south and right photo facing west. Reclaimed well pad vegetation has not yet established and will need to be re-inspected.

Inspection Photos
Location Name: Frank 1-21C
Location ID: 323096



Photo 5. Overview photo of the tank battery taken at ground level from the northern edge looking south.

Inspection Photos
Location Name: Frank 1-21C
Location ID: 323096



Photo 6. Reference area to the west of the well pad and tank battery.