

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type WELLHEAD

Comment: 6' chain link with barb wire

Corrective Action:

Date: _____

Equipment:

corrective date

Type: Ancillary equipment # 1

Comment: Automation

Corrective Action:

Date: _____

Type: Bradenhead # 2

Comment: Plumbed to surface

Corrective Action:

Date: _____

Type: Plunger Lift # 2

Comment:

Corrective Action:

Date: _____

Venting:

Yes/No NO

Comment:

Corrective Action:

Date: _____

Flaring:

Type

Comment:

Corrective Action:

Date: _____

Inspected Facilities

Facility ID: 431462 Type: WELL API Number: 123-36622 Status: PR Insp. Status: PR

Facility ID: 431463 Type: WELL API Number: 123-36623 Status: PR Insp. Status: PR

Facility ID: 431508 Type: WELL API Number: 123-36633 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 11/24/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: None

End Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules. At time of inspection weather conditions were clear, cold, recent snow.	medinaj	01/26/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699503514	Inspection pictures	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5649683