

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

01/28/2022

Submitted Date:

01/28/2022

Document Number:

699503515

FIELD INSPECTION FORM
 Loc ID 444280 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|------------------------------|-----------------|
| , | | COGCCInspections@Oxy.co m | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------|-------------|
| 444275 | WELL | PR | 10/01/2019 | OW | 123-42537 | MEESE 1C-14HZ | PR |
| 444276 | WELL | PR | 01/01/2020 | OW | 123-42538 | MEESE STATE 38C-35HZ | PR |
| 444277 | WELL | PR | 10/01/2019 | OW | 123-42539 | MEESE 37C-35HZ | PR |
| 444278 | WELL | PR | 10/01/2020 | OW | 123-42540 | MEESE 16N-35HZ | PR |
| 444279 | WELL | PR | 07/01/2021 | OW | 123-42541 | MEESE 26N-14HZ | PR |
| 444281 | WELL | PR | 10/01/2018 | OW | 123-42542 | MEESE 1N-14HZ | PR |
| 444282 | WELL | PR | 08/03/2017 | OW | 123-42543 | MEESE 27N-14HZ | PR |
| 444283 | WELL | PR | 08/09/2017 | OW | 123-42544 | MEESE STATE 38N-35HZ | PR |

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type WELLHEAD

Comment: Red Agricultural fencing

Corrective Action:

Date:

Equipment:

corrective date

Type: Ancillary equipment

1

Comment: Electric / automation

Corrective Action:

Date:

Type: Plunger Lift

7

Comment:

Corrective Action:

Date:

Type: Pump Jack

1

Comment:

Corrective Action:

Date:

Type: Prime Mover

1

Comment: Electric motor

Corrective Action:

Date:

Type: Bradenhead

8

Comment: Plumbed to surface

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

| | | | | |
|---------------------|------------|-----------------------|------------|------------------|
| Facility ID: 444275 | Type: WELL | API Number: 123-42537 | Status: PR | Insp. Status: PR |
| Facility ID: 444276 | Type: WELL | API Number: 123-42538 | Status: PR | Insp. Status: PR |
| Facility ID: 444277 | Type: WELL | API Number: 123-42539 | Status: PR | Insp. Status: PR |
| Facility ID: 444278 | Type: WELL | API Number: 123-42540 | Status: PR | Insp. Status: PR |
| Facility ID: 444279 | Type: WELL | API Number: 123-42541 | Status: PR | Insp. Status: PR |
| Facility ID: 444281 | Type: WELL | API Number: 123-42542 | Status: PR | Insp. Status: PR |
| Facility ID: 444282 | Type: WELL | API Number: 123-42543 | Status: PR | Insp. Status: PR |
| Facility ID: 444283 | Type: WELL | API Number: 123-42544 | Status: PR | Insp. Status: PR |

Producing Well

| | |
|--------------------|-------|
| Comment: PR | |
| Corrective Action: | Date: |

BradenHead

| | |
|------------------------------------|------------------------------|
| Date of Last Brhd Test: 08/19/2021 | Annual Brhd Completed? Yes |
| Last Brhd Test Results | Initial Surf Csg Pressure: 0 |
| | Fluid Type: None |
| | End Surf Csg Pressure: -- |
| Comment: | |
| Corrective Action: | Date: |

COGCC Comments

| Comment | User | Date |
|---------------------------------------------------------------------------------------------------------------------------------------------------------|---------|------------|
| At time of inspection location appears to be in compliance with COGCC rules. At time of inspection weather conditions were clear, cold, recent snow. | medinaj | 01/28/2022 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 699503516 | Inspection Pictures | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5649684 |