

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Prime Mover

1

corrective date

Comment: [Electric motor](#)

Corrective Action:

Date:

Type: Pump Jack

1

Comment:

Corrective Action:

Date:

Type: Bradenhead

1

Comment: [Plumbed to surface](#)

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment: [Electric equipment](#)

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 241372 Type: WELL API Number: 123-09161 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

BradenHead

Date of Last Brhd Test: 08/26/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: -- Fluid Type: _____

End Surf Csg Pressure: --

Comment:

Corrective Action: Date: _____

COGCC Comments

| Comment | User | Date |
|---|---------|------------|
| At time of inspection location appears to be in compliance with COGCC rules. At time of inspection weather conditions were clear, cold, recent snow. | medinaj | 01/28/2022 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------------|---|
| 699503520 | Inspection Pictures | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5649686 |