

# Inspection Photos

API: 009-06236

Operator: DOVER ATWOOD CORPORATION

Inspection Date: 1/31/2022



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 009-06236 | Date: 1/31/2022

## Inspection Photos



**Photo 1.** Facing northeast toward wellsite.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06236 | Date: 1/31/2022

## Inspection Photos



**Photo 2.** The tank on the location is busted apart and there is a solidified oily substance inside the tank which appears to have spilled out.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06236 | Date: 1/31/2022

## Inspection Photos



**Photo 3.** This photo shows the solidified oily substance inside the tank.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06236 | Date: 1/31/2022

## Inspection Photos



**Photo 4.** There is weed debris around the equipment which is a fire hazard.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06236 | Date: 1/31/2022

## Inspection Photos



**Photo 5.** The well sign has fallen over and needs to be properly installed.



**Photo 6.** The emergency contact number was not valid and does not meet the signage requirements.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06236 | Date: 1/31/2022