

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS /SG 33-32

Location ID: 413524



Photo #5838 from entrance to location.



Photo #5850 Debris located by wellheads.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS /SG 33-32

Location ID: 413524



Photo #5849 No battery sign located at the tank battery.



Photo #5838 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS /SG 33-32

Location ID: 413524



Photo #5840 Gavel has been added to access road.



Photo #5809 from inspection #699804078 inspection conducted on 1/27/22.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS /SG 33-32

Location ID: 413524



Photo #5842 Insufficient tracking BMP located at entrance to location.



Photo #5804 from inspection #699804078 inspection conducted on 1/27/22.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS /SG 33-32

Location ID: 413524



Photo #5843 Tracking occurring on to highway 6.



Photo #5810 from inspection #699804078 inspection conducted on 1/27/22.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS /SG 33-32

Location ID: 413524



Photo #5844 Tracking continuing on to highway 6.



Photo #5812 from inspection #699804078 inspection conducted on 1/27/22.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS /SG 33-32

Location ID: 413524



Photo #5845 Tracking occurring from location and access road for approximately 100 yards.



Photo #5811 from inspection #699804078 inspection conducted on 1/27/22.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS /SG 33-32

Location ID: 413524



Photo #5846 Tracking occurring on highway 6 continued.



Photo #5847 The transportation of sediment continued for approximately 100 yards.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS /SG 33-32

Location ID: 413524



Photo #5848 Tracking occurring on highway 6 continued.