

Inspection Photos

ID# 441082

Operator: DOVER ATWOOD CORPORATION

Inspection Date: 1/31/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

ID# 441082 | Date: 1/31/2022

Inspection Photos



Photo 1. Facing northeast toward the location. The disturbed location has not been reclaimed. Previous corrective actions were not performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID# 441082 | Date: 1/31/2022

Inspection Photos



Photo 2. Facing southeast at the location. Soils are compacted and the location has not been reclaimed. Previous corrective actions were not performed. Soils must be decompacted by cross ripping to a depth of 18 inches.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID# 441082 | Date: 1/31/2022

Inspection Photos



Photo 3. There is various debris that remains around the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID# 441082 | Date: 1/31/2022

Inspection Photos



Photo 4. There are gravel and soil piles that remain at the north side of the location. The piles need to be removed. There are undesirable weeds growing on the piles.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID# 441082 | Date: 1/31/2022

Inspection Photos



Photo 5. There is cement debris that remains on the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID# 441082 | Date: 1/31/2022

Inspection Photos



Photo 6. There are piles of manure and material left on the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID# 441082 | Date: 1/31/2022

Inspection Photos



Photo 7. Facing west at the location. Soils are compacted and the location has not been reclaimed. Previous corrective actions were not performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID# 441082 | Date: 1/31/2022

Inspection Photos



Photo 8. There is a cleanout junction 1850 ft. north of the pipeline which is associated with the former gas compressor station and must be removed. Photo from previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID# 441082 | Date: 1/31/2022

Inspection Photos



Photo 9. Facing east toward the surround reference vegetation which consists of desirable vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID# 441082 | Date: 1/31/2022