

Inspection Photos

API: 009-06669

Operator: JETTA OPERATING COMPANY

Inspection Date: 2/1/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06669 | Date: 2/1/2022

Inspection Photos



Photo 1. Facing north at the location. The location consists almost entirely of undesirable weeds. (Kochia sp., Russian thistle)



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06669 | Date: 2/1/2022

Inspection Photos



Photo 2. Center of the location facing west. The perennial vegetation has not reestablished and there is undesirable weeds throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06669 | Date: 2/1/2022

Inspection Photos



Photo 3. Center of the location facing south. The perennial vegetation has not reestablished and there is undesirable weeds throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06669 | Date: 2/1/2022

Inspection Photos



Photo 4. Center of the location facing east. The perennial vegetation has not reestablished and there is undesirable weeds throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06669 | Date: 2/1/2022

Inspection Photos



Photo 5. View of groundcover shows undesirable weeds consisting of Kocki sp. and Russian thistle.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06669 | Date: 2/1/2022

Inspection Photos



Photo 6. Facing southwest off the location. The surrounding field has perennial vegetation growth (Sand drop seed).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06669 | Date: 2/1/2022