

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/31/2022

Submitted Date:

02/03/2022

Document Number:

701102614

**FIELD INSPECTION FORM**

Loc ID: 312609 Inspector Name: LONGWORTH, MIKE On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 53255  
Name of Operator: MARALEX RESOURCES INC  
Address: P O BOX 338  
City: IGNACIO State: CO Zip: 81137

**Findings:**

- 9 Number of Comments
- 6 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Hahn, Travis		thahn@maralexinc.com	All Inspections
Byers, Jim		jbyers@blm.gov	
Graves, Jim		mrinc20@maralexinc.com	
, Engineering		dnr_cogccengineering@state.co.us	All engineering

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222011	WELL	SI	05/01/2012	GW	077-08613	SOUTH SHALE RIDGE 7-24	SI

**General Comment:**

COGCC Follow Up Inspection Report Summary  
Follow up to 12/07/020 inspection # 699802220  
Uncorrected action item(s)  
• Last produced April 2010. Last MIT performed on 2/19/15. MIT required.  
During this inspection the following compliance issues were observed:  
• EMS (911) not posted on battery sign.  
• Tank battery sign is illegible and does not meet Rule 605.e.  
• Tank label is illegible.  
• Weeds around well, production equipment, and tank battery.  
• Access road is rutted and lacks stabilization. Road ditch needs maintained.  
A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Tank label is illegible.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	05/06/2022
Type	BATTERY		
Comment:	Tank battery sign is illegible and does not meet Rule 605.e.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	05/06/2022

**Emergency Contact Number:**

Comment: EMS (911) not posted on battery sign.

Corrective Action: Install sign to comply with Rule 605.e.

Date: 03/05/2022

**Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds around well, production equipment, and tank battery.		
Corrective Action:	Comply with Rule 606	Date:	02/20/2022

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type			corrective date
Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
	1		Open Top		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	Not posted
Other (Capacity)	Not posted
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 222011 Type: WELL API Number: 077-08613 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Last produced April 2010. Last MIT performed on 2/19/15.

Corrective Action: A mechanical integrity test shall be performed on each shut-in well on 5 year intervals from the date the initial mechanical integrity test was performed. Perform MIT on well.

Date: 05/15/2020

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						
		Ditches				
		Compaction				

Comment: [Access road is rutted and lacks stabilization. Road ditch needs maintained.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.\(2\)C](#)

Date: 02/19/2022

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701102622	Inspection 701102614 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5654008">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5654008</a>