

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/02/2022

Submitted Date:

02/02/2022

Document Number:

700703818

FIELD INSPECTION FORMLoc ID: 420296 Inspector Name: Ramsey, Scott On-Site Inspection: ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10531

Name of Operator: GRIZZLY OPERATING LLC

Address: 5847 SAN FELIPE #3000

City: HOUSTON State: TX Zip: 77057

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

18 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
420317	WELL	PR	04/18/2012	GW	045-20119	CBS 31C-21-692	PR
420318	WELL	PR	03/23/2012	GW	045-20120	CBS 32B-21-692	PR
420319	WELL	PR	04/18/2012	GW	045-20121	CBS 41C-21-692	PR
420320	WELL	PR	04/18/2012	GW	045-20122	CBS 31B-21-692	PR
420321	WELL	PR	04/18/2012	GW	045-20123	CBS 41D-21-692	PR
420322	WELL	PR	03/22/2012	GW	045-20124	CBS 41B-21-692	PR
420323	WELL	PR	04/18/2012	GW	045-20125	CBS 31D-21-692	PR
420324	WELL	PR	03/23/2012	GW	045-20126	CBS 42D-21-692	PR
420325	WELL	PR	03/22/2012	GW	045-20127	CBS 32D-21-692	PR
420326	WELL	PR	03/23/2012	GW	045-20128	CBS 42B-21-692	PR

General Comment:**COGCC Inspection Report Summary**

On Wednesday 2/2/2022 at approximately 1000, I, Inspector Scott Ramsey, conducted a routine inspection at TEP CB Land Tract 5, at Location # 420296 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad.

Location is snow covered in areas at the time of inspection and Plowed.

During this inspection the following possible compliance issues were observed:

1. Load lines missing bull plugs/caps

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action	L		Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of fluid. Labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	OTHER		
Comment:	Load lines missing bull plugs/caps		
Corrective Action:	Comply with rule 603.i.		Date: 03/18/2022
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Plunger Lift	# 10		corrective date
Comment:			

Corrective Action:		Date:	
Type: Bird Protectors	# 9		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 10		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	One chemical tank in plastic containment and one 500 gallon methanol tank in metal containment		
Corrective Action:		Date:	
Type: Emission Control Device	# 0		
Comment:	ECD has been removed. Piping and knock out bottle are still in place.		
Corrective Action:		Date:	
Type: Bradenhead	# 10		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	6	500 BBLs	HEATED STEEL AST		,
Comment:	2 tanks are not heated				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	420317	Type:	WELL	API Number:	045-20119	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	420318	Type:	WELL	API Number:	045-20120	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	420319	Type:	WELL	API Number:	045-20121	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	420320	Type:	WELL	API Number:	045-20122	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	420321	Type:	WELL	API Number:	045-20123	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	420322	Type:	WELL	API Number:	045-20124	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	420323	Type:	WELL	API Number:	045-20125	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	420324	Type:	WELL	API Number:	045-20126	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			

Facility ID:	420325	Type:	WELL	API Number:	045-20127	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: Producing

Corrective Action:

Date:

Facility ID:	420326	Type:	WELL	API Number:	045-20128	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: Producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Limited storm water inspection due to snow cover](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700703823	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5654830