

**Inspection Photos**  
**Location Name: UPRR 48 PAN AM H#1**  
**Location ID: 319999**



**Photo#1 Production Tanks**



**Photo#2 Pumpjack/Wellhead**



Inspection Photos  
Location Name: UPRR 48 PAN AM H#1  
Location ID: 319999



Photo#3 Separator/Gas Meter



Photo#4 Stained Soil around wellhead

Inspection Photos  
Location Name: UPRR 48 PAN AM H#1  
Location ID: 319999



**Photo#5 Corrective Action: No Secondary Containment under chemical tank. Repair or install berms or other secondary containment devices per Rule 603.o.**



**Photo#6 Open remediation work**

**Inspection Photos**  
**Location Name: UPRR 48 PAN AM H#1**  
**Location ID: 319999**



**Photo#7 Open remediation work/Stained soil**



**Photo#8 Open remediation work/Open hole where concrete water vault was.**

**Inspection Photos**  
**Location Name: UPRR 48 PAN AM H#1**  
**Location ID: 319999**



**Photo#9 Broken concrete vault**



**Photo#10 Open remediation work/No Safety fencing around hole.**

**Inspection Photos**  
**Location Name: UPRR 48 PAN AM H#1**  
**Location ID: 319999**



**Photo#11 Pile of contaminated soil**



**Photo#12 Pile of contaminated soil**

**Inspection Photos**  
**Location Name: UPRR 48 PAN AM H#1**  
**Location ID: 319999**



**Photo#12 Pile of contaminated soil**



**Photo#13 Pile of contaminated soil**



**Inspection Photos**  
**Location Name: UPRR 48 PAN AM H#1**  
**Location ID: 319999**



**Photo#14 Corrective Action: 603.i.**  
**All loadlines will be bullplugged or capped.**



**Photo#15 Corrective Action: Comply with Rule 606, Statewide unnecessary equipment, weeds, waste, and trash requirements**