

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/01/2022

Submitted Date:

02/04/2022

Document Number:

687400829**FIELD INSPECTION FORM**Loc ID 319999 Inspector Name: Huck, Keith On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**13 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Espinosa, Bill		billespinosa30@yahoo.com	<a href="#">Inspections</a>
Ingvie, Ed	(303) 680-4725	ed@renegadeoilandgas.com	<a href="#">All Inspections</a>
Chesson, Robert		robert.chesson@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202201	WELL	PR	06/01/2021	GW	001-07606	UPRR 48 PAN AM H 1	SI

**General Comment:**

### Location

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment on backside of production tanks		
Corrective Action:	Corrective Action: Comply with Rule 606, Statewide unnecessary equipment, weeds, waste, and trash requirements. See Photo#15	Date:	02/21/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Square pipe		
Corrective Action:		Date:	

**Equipment:**

			corrective date
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Type: Bradenhead	# 1	
Comment:	Appears to be plumbed to surface	
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	CONCRETE SUMP/VAULT		,
Comment:	Appears that the operator has removed vault in berm on the south side for tanks. Appears to have stained soil in open hole and in the dirt that was removed. COGCC Rule 1002. is not being followed, and there appears to be no BMPs in place - fencing around open hole, proper storage of dirt that appears to have stained soil in it, No storm water management of removed soil and around the removed vault.				
Corrective Action:	Follow what the EPS Team at the COGCC wants you to do.				Date: 04/01/2022

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		39.840823,-104.378625
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Sufficient	Inadequate
Comment:	Berms will need to be repaired once remediation work is completed.			
Corrective Action:	Follow what the EPS Team at the COGCC wants you to do.			Date: 04/01/2022

**Wells Served By Facilities Above**

API Number
001-07606

**AirsID**

API Number	AirsID
------------	--------

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

--

**Inspected Facilities**Facility ID: 202201 Type: WELL API Number: 001-07606 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: EQUIPMENT ONSITEComment: SICorrective Action: Date: **COGCC Comments**

## Comment

## User

## Date

**COGCC Inspection Report Summary**

On Tuesday February 1st, 2022 at approximately 11:57am. I, Inspector Keith Huck, conducted an on-site inspection at (UPRR 49Pan Am H1) (Renegade Oil & Gas Company), at

API #(001-07606) in Adams County Colorado.

While there, I observed a shut in well.

During this inspection the following possible compliance issues were observed:

Appears that the operator has removed vault in berm on the south side for tanks. Appears to have stained soil in open hole and in the dirt that was removed. COGCC Rule 1002. is not being followed, and there appears to be no BMPs in place - fencing around open hole, proper storage of dirt that appears to have stained soil in it, No storm water management of removed soil and around the removed vault. This matter has been forwarded to the EPS team Bob Chesson and he contacted Renegade and they are in the process of submitting a Form 27. Bob will let us know once that is processed.

Stained soil around well head. Control and contain spills/releases and clean up per Rule 905.e. Corrective Action Date 02/21/2022 to remove stained soil. See attached photo #4 Foundation Energy Management is listed as owner on COGCC web site but Renegade oil and gas company well signs are at the location and at pump jack sight. According to Doc #699502185 on 1/25/2021 there is a form #10 being processed.

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

huckk

02/04/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687400830	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5655347">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5655347</a>