

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402914596

Date Received:

01/03/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

General

sjninspections@ikavenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693903914

Inspection Date: 11/30/2021

FIR Submit Date: 12/01/2021

FIR Status: _____

Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 443658

Location Name: Ford H Number: 1,2 & 3 County: LA PLATA

Qtrqr: SENW Sec: 10 Twp: 33N Range: 8W Meridian: N

Latitude: 37.121199 Longitude: -107.707950

FACILITY - API Number: 05-067-00 Facility ID: 443657

Facility Name: Ford H Number: 3

Qtrqr: SENW Sec: 10 Twp: 33N Range: 8W Meridian: N

Latitude: 37.121199 Longitude: -107.707950

CORRECTIVE ACTIONS:

1 ☒ CA# 158253

Corrective Action: -Remove gravel and rock deposits from the intermittent stream and discharged areas down-slope of the access road. Stream is an intermittent stream and rock is considered a discharge into Waters of the State. Any damage to vegetation during gravel/rock removal process will require further seeding and reclamation. Corrective action date: 12/30/2021

Date: 12/30/2021

Response: CA COMPLETED

Date of Completion: 12/28/2021

Operator
Comment:

Removed gravel and sediment that had washed down drainage.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 158254

Corrective Action: -Stormwater controls need to be installed to stabilize erosion along the access road and within the southeastern corner of the project area. This includes properly diverting stormwater flows, installation of BMPs, and stabilization of culvert inlets and outlets. All stormwater controls need to be selected, sized, installed, and maintained according to good engineering practices. Current practices and materials are not adequate. Corrective action date: 12/30/2021.

Date: 12/30/2021

Response: CA COMPLETED

Date of Completion: 12/28/2021

Operator
Comment:

Armored inlet and outlet of culverts to help prevent future erosion and wash outs. Reestablished bar ditch along road to prevent water from running across road.
Repaired road. Repaired waddle

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CAs Completed

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Karin Rhodes

Signed: _____

Title: admin asst

Date: 1/3/2022 8:38:20 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402914596	FIR RESOLUTION SUBMITTED
402914600	ford h 1-3 work completed

Total Attach: 2 Files