

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNION-67S96W /3SWNE

Location ID: 323956



Photo #5866 from entrance to location.



Photo #5869 Vent pipe on tank open ended.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNION-67S96W /3SWNE

Location ID: 323956



Photo #5867 Location lacks stabilization.



Photo #5868 Insufficient tracking BMP at entrance to location.