

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/28/2022

Submitted Date:

02/07/2022

Document Number:

699602676

**FIELD INSPECTION FORM**Loc ID 332082 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections
,		dnr_cogccengineering@state. co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270031	WELL	PR	11/01/2019	OW	123-21811	UHRICH 14-29	PA

**General Comment:**

This is a PLUGGED &amp; ABANDONED WELL / CEMENTING inspection.

Well(s): 1: Plugged &amp; Abandoned | PA.

Plugging Operations / Cementing. Final plugs, cement to surface.

Battery: Inactive | Shut-down.

Inactive Battery SE corner GPS coordinates: 40.449914 / -104.581087

This Field Inspection Report supersedes Field Inspection Report doc. #699602666.

Inspection date was incorrect.

**Location****Lease Road:**

Type	Access		
comment:	Adequate		
Corrective Action:		Date:	

Overall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Jobsite safety signage present.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Plunger Lift	# 0		corrective date
Comment:	Plugged & Abandoned   PA. Equipoment removed.		
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 270031 Type: WELL API Number: 123-21811 Status: PR Insp. Status: PA

**Cement**Cement ContractorContractor Name: A-Plus

Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_

Circulate to Surface: \_\_\_\_\_

Cement Fall Back: \_\_\_\_\_

Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Plugging OperationsDepth Plugs(feet range): 2,000'-12'-0'Cement Volume (sx): 336 sxsGood Return During Job: YESCement Type: Class "G-Neat" 15.8#

Comment: [Workover Contractor: A-Plus. Rig #12.](#)  
[Cementing Contractor: A-Plus.](#)

Reference:[Form 42 on file. Plugging start date: 01/19/2022. Approved.](#)[Form 6N on file. Notice of intent to Abandon date: 11/23/2021. Approved.](#)Cement to surface:[SAFETY MEETING,CHECK PSI,CSG O,SURFACE O,RUWL,PU 4.5 JET CUTTER & CUT CSG](#)[@951,RDWL,CONDITION HOLE WITH 10 BBLS CHEM WASH & 70 BBLS FRESH WATER,,PUMP 336 SACS](#)[OR 69 BBLS OF 15.8# G-NEAT GMT @1.15 YIELD TO SURFACE,NDBOP,INSTAL NIGHT CAP,TOP OFF](#)[CMT,SWI,RIG DOWN,CLEAN UP LOC,MRO,FINAL REPORT .](#)

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Completion**

Operation: \_\_\_\_\_

Date Flowback: \_\_\_\_\_

Contractor: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<b>COGCC Inspection Report Summary:</b>  On TUE 01/28/2022 at approximately 14:20 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: UHRICH-66N64W /29SESW Location ID: 332082 Well Name(s): Uhrich 14-29. API: 05-123-21811. Location County: Weld County, Colorado Weather: Sunny, wet w/ mud, snow from prior storm.  While there, I observed: Well(s): 1: Plugged & Abandoned   PA. Plugging Operations / Cementing. Final plugs, cement to surface. Battery: Inactive   Shut-down. Inactive Battery SE corner GPS coordinates: 40.449914 / -104.581087  This Field Inspection Report supersedes Field Inspection Report doc. #699602666. Inspection date was incorrect.  During this inspection, NO possible compliance issues were observed.  This is a summary of the inspection report.	evinsb	02/07/2022

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699602677	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5656862">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5656862</a>