

HILL RANCH 34-16 API# 05-071-07815 – OGRIS OPERATING LLC
OGCC OPERATOR NUMBER 10758 - DATE: NOVEMBER 05, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695104890



MAINTENANCE WAS CONDUCTED TO THE PUMPING JACK MOTOR TO STOP THE OIL LEAK. THE FLUID ACCUMULATION WAS REMOVED FROM CONTAINMENT. THE IMPACTED SOIL NEXT TO THE CONCRETE BASE WAS REMOVED FROM THE LOCATION AND THE SELF-INSPECTION PROCESS WAS REVIEWED.

HILL RANCH 34-16 API# 05-071-07815 – OGRIS OPERATING LLC
OGCC OPERATOR NUMBER 10758 - DATE: FEBRUARY 4, 2022
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695104890



THE STAINS ON THE CONCRETE BASE OF THE PUMPING JACK WERE REMOVED.

HILL RANCH 34-16 API# 05-071-07815 – OGRIS OPERATING LLC
OGCC OPERATOR NUMBER 10758 - DATE: DECEMBER 13, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695104890



THE IMPACTED SOIL WAS REMOVED AND GROUND CLEANED UP NEAR THE PUMPING JACK.

HILL RANCH 34-16 API# 05-071-07815 – OGRIS OPERATING LLC
OGCC OPERATOR NUMBER 10758 - DATE: NOVEMBER 05, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695104890




THE LOCATION SIGN WAS REPLACED IN ACCORDANCE WITH THE NEW RULES.

HILL RANCH 34-16 API# 05-071-07815 – OGRIS OPERATING LLC
OGCC OPERATOR NUMBER 10758 - DATE: OCTOBER 12, 2021
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695104890



THE SAND WAS REMOVED FROM LOCATION IN ACCORDANCE WITH THE SAND – PREMIUM WHITE MSDS.

HILL RANCH 34-16 API# 05-071-07815 – OGRIS OPERATING LLC
OGCC OPERATOR NUMBER 10758 - DATE: JANUARY 11, 2022
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695104890



THE PUMPING JACK MOTOR WAS FOUND TO BE LEAKING AGAIN. THE ENGINE WAS REPLACED AND NO LEAKS WERE DETECTED.