

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/03/2022

Submitted Date:

02/07/2022

Document Number:

701004435**FIELD INSPECTION FORM**Loc ID 324852 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 16830

Name of Operator: CHOLLA PRODUCTION LLC

Address: 10390 BRADFORD RD #201

City: LITTLETON State: CO Zip: 80127

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

17 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Goff, Bill	303-249-0430	cholla_production@msn.com	
Akers, Tracy	719-342-1813	takers@mulldrilling.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213221	WELL	PR	07/03/1997	OW	061-06583	WICKERSHAM 1	PR

General Comment:

Routine Inspection

Location

Lease Road:			
Type	Access		
comment:	Dirt road through farm ground		
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Lease sign by tanks		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Stickers and stencils on tanks		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	<input style="width: 500px;" type="text"/>
Corrective Action:	<input style="width: 500px;" type="text"/> Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	National 228		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:	ECD next to separator		
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Phase converter, electric panel and propane tank by separator		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		

Comment:	Separator on west side of tanks	Date:	
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLS	FIBERGLASS AST		38.469520,-102.436130

Comment:	Produced water tank on west side of gun barrel	Date:	
Corrective Action:		Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:	Shared berms	Date:	
Corrective Action:		Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	200 BBLS	FIBERGLASS AST		38.469520,-102.436130

Comment:	Gun barrel on west side of oil tanks	Date:	
Corrective Action:		Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:	Shared berms	Date:	
Corrective Action:		Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	200 BBLS	FIBERGLASS AST		38.469520,-102.436130

Comment:	2 East tanks	Date:	
Corrective Action:		Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
<u>Venting:</u>					
Yes/No					
Comment:					
Corrective Action:				Date:	
<u>Flaring:</u>					
Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities									
Facility ID:	213221	Type:	WELL	API Number:	061-06583	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Tank battery is 2700' SW @ 38.469520/-102.436130 by CR 59								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: [Access to wellhead is farmed over](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701004452	location photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5657374