

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/07/2022

Submitted Date:

02/07/2022

Document Number:

693200981

**FIELD INSPECTION FORM**

Loc ID 335579 Inspector Name: Murray, Richard On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10456  
Name of Operator: CAERUS PICEANCE LLC  
Address: 1001 17TH STREET #1600  
City: DENVER State: CO Zip: 80202

**Findings:**

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	<a href="#">Engineering Integrity Supervisor</a>
, Caerus		kmizespansky@caerusoilandgas.com	
Caerus		COGCC.inspections@caerusoilandgas.com	<a href="#">All Piceance inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
481515	SPILL OR RELEASE	CL	02/04/2022		-	E19-595 (8C) Flowline Release	EG

**General Comment:**

[Engineering Integrity Inspection performed on February 7, 2022; in response to Initial form 19-release report Doc # 402940120](#)

**Inspected Facilities**

Facility ID: 481515 Type: SPILL OR API Number: - Status: CL Insp. Status: EG

**Flowline**

#1	Type: Dump Line	1 of Lines
----	-----------------	------------

Flowline Description

Flowline Type: Dump Line Size: 2" Material: Carbon Steel  
 Variance: No Age: 1-5 Yrs Contents: Multiphase

Integrity Summary

Failures: Other Spills: Yes Repairs Made: Yes  
 Coatings: Cathodic Protection: No

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

1101. Installation and Reclamation  1102. Operations, Maintenance, and Repair  1103. Abandonment

Comment: Provide Root Cause when information becomes available. Via email to Western Integrity inspector  
 Provide pressure test results before returning back into service, Via email to Western Integrity inspector

Corrective Action:

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693200982	Location Photo 1	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5657621">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5657621</a>
693200983	Location Photo 2	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5657622">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5657622</a>