

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/08/2022

Submitted Date:

02/08/2022

Document Number:

697005230**FIELD INSPECTION FORM**Loc ID 327974 Inspector Name: Peterson, Tom On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                    | Comment |
|--------------|-------|--------------------------|---------|
| ,            |       | cogccinspection@pdce.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name               | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------------|-------------|
| 247586      | WELL | SI     | 04/01/2020  | GW         | 123-15383 | UPRR 21 PAN AM GAS UT /F/ 2 | SI          |

**General Comment:**

**Location**Overall Good: ☒

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | WELLHEAD             |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | BATTERY              |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                |      |        |  |  |  |
|----------------|------|--------|--|--|--|
| <b>Spills:</b> |      |        |  |  |  |
| Type           | Area | Volume |  |  |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |          |       |  |
|--------------------|----------|-------|--|
| <b>Fencing/:</b>   |          |       |  |
| Type               | WELLHEAD |       |  |
| Comment:           | Panel    |       |  |
| Corrective Action: |          | Date: |  |

|                           |                  |       |                 |
|---------------------------|------------------|-------|-----------------|
| <b>Equipment:</b>         |                  |       | corrective date |
| Type: Flow Line           | # 1              |       |                 |
| Comment:                  |                  |       |                 |
| Corrective Action:        |                  | Date: |                 |
| Type: Pig Station         | # 1              |       |                 |
| Comment:                  |                  |       |                 |
| Corrective Action:        |                  | Date: |                 |
| Type: Bird Protectors     | # 1              |       |                 |
| Comment:                  |                  |       |                 |
| Corrective Action:        |                  | Date: |                 |
| Type: Ancillary equipment | # 1              |       |                 |
| Comment:                  | Automation array |       |                 |
| Corrective Action:        |                  | Date: |                 |
| Type: Gas Meter Run       | # 1              |       |                 |

|                                   |     |                              |  |       |  |
|-----------------------------------|-----|------------------------------|--|-------|--|
| Comment:                          |     | Calibration card is current. |  | Date: |  |
| Corrective Action:                |     |                              |  | Date: |  |
| Type: Horizontal Heated Separator | # 1 |                              |  |       |  |
| Comment:                          |     |                              |  | Date: |  |
| Corrective Action:                |     |                              |  | Date: |  |
| Type: Plunger Lift                | # 1 |                              |  |       |  |
| Comment:                          |     |                              |  | Date: |  |
| Corrective Action:                |     |                              |  | Date: |  |

**Tanks and Berms:**

| Contents           | # | Capacity              | Type           | Tank ID | SE GPS |
|--------------------|---|-----------------------|----------------|---------|--------|
| PRODUCED WATER     | 1 | 100 BBLs              | PBV FIBERGLASS |         | ,      |
| Comment:           |   | Anchored and grounded |                |         |        |
| Corrective Action: |   |                       |                | Date:   |        |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

| Contents           | # | Capacity | Type      | Tank ID | SE GPS                |
|--------------------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL          | 1 | 300 BBLs | STEEL AST |         | 40.290340,-104.749730 |
| Comment:           |   |          |           |         |                       |
| Corrective Action: |   |          |           | Date:   |                       |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|        |    |  |
|--------|----|--|
| Yes/No | NO |  |
|--------|----|--|

|                    |  |       |  |
|--------------------|--|-------|--|
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**Facility ID: 247586 Type: WELL API Number: 123-15383 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**Date of Last Brhd Test: 06/28/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 697005231    | Photos      | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5658591">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5658591</a> |