

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/01/2022

Submitted Date:

02/02/2022

Document Number:

700703810**FIELD INSPECTION FORM**

Loc ID 311534 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: 1058 COUNTY ROAD 215City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210460	WELL	PR	01/01/2020	GW	045-06216	FEDERAL-RULISON 8	PR
210468	WELL	PR	01/01/2020	GW	045-06224	FEDERAL-RULISON 122	PR
468800	WELL	XX	10/22/2019		045-24287	FEDERAL RWF 21-13	XX
468801	WELL	XX	10/22/2019		045-24288	FEDERAL RWF 313-12	XX
468802	WELL	XX	10/22/2019		045-24289	FEDERAL RWF 543-11	XX
468803	WELL	XX	10/22/2019		045-24290	FEDERAL RWF 24-12	XX
468804	WELL	XX	10/22/2019		045-24291	FEDERAL RWF 324-12	XX
468805	WELL	XX	10/22/2019		045-24292	FEDERAL RWF 343-11	XX
468806	WELL	XX	10/22/2019		045-24293	FEDERAL RWF 421-13	XX
468807	WELL	XX	10/22/2019		045-24294	FEDERAL RWF 444-11	XX
468808	WELL	XX	10/22/2019		045-24295	FEDERAL RWF 344-11	XX
468809	WELL	XX	10/22/2019		045-24296	FEDERAL RWF 411-13	XX
468810	WELL	XX	10/22/2019		045-24297	FEDERAL RWF 44-11	XX
468811	WELL	XX	10/22/2019		045-24298	FEDERAL RWF 321-13	XX
468812	WELL	XX	10/22/2019		045-24299	FEDERAL RWF 544-11	XX

General Comment:

COGCC Inspection Report Summary

On Tuesday 2/1/2022 at approximately 1200, I, Inspector Scott Ramsey, conducted a routine inspection at TEP Rulison 8, at Location # 311534 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad.

Location is snow covered in areas at the time of inspection.

During this inspection the following possible compliance issues were observed:

1. Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.
2. Valve on well head is leaking gas.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:	snow covered		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Valve on well head is leaking gas.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition.	Date:	02/04/2022

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Plunger Lift	# 2		
Comment:	One well not on plunger lift		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		

Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	YES		
Comment:	Wellhead See housekeeping		
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	210460	Type:	WELL	API Number:	045-06216	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	210468	Type:	WELL	API Number:	045-06224	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	468800	Type:	WELL	API Number:	045-24287	Status:	XX	Insp. Status:	XX
Facility ID:	468801	Type:	WELL	API Number:	045-24288	Status:	XX	Insp. Status:	XX
Facility ID:	468802	Type:	WELL	API Number:	045-24289	Status:	XX	Insp. Status:	XX
Facility ID:	468803	Type:	WELL	API Number:	045-24290	Status:	XX	Insp. Status:	XX
Facility ID:	468804	Type:	WELL	API Number:	045-24291	Status:	XX	Insp. Status:	XX
Facility ID:	468805	Type:	WELL	API Number:	045-24292	Status:	XX	Insp. Status:	XX
Facility ID:	468806	Type:	WELL	API Number:	045-24293	Status:	XX	Insp. Status:	XX
Facility ID:	468807	Type:	WELL	API Number:	045-24294	Status:	XX	Insp. Status:	XX
Facility ID:	468808	Type:	WELL	API Number:	045-24295	Status:	XX	Insp. Status:	XX
Facility ID:	468809	Type:	WELL	API Number:	045-24296	Status:	XX	Insp. Status:	XX
Facility ID:	468810	Type:	WELL	API Number:	045-24297	Status:	XX	Insp. Status:	XX
Facility ID:	468811	Type:	WELL	API Number:	045-24298	Status:	XX	Insp. Status:	XX
Facility ID:	468812	Type:	WELL	API Number:	045-24299	Status:	XX	Insp. Status:	XX

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Limited storm water inspection due to snow cover

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402945416	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5652969
700703813	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5652965