

Inspection Photos
Location Name: Myers 19-11HA
Location ID: 441283



Photo 1. Overview of location taken facing southwest.



Inspection Photos
Location Name: Myers 19-11HA
Location ID: 441283



Photo 2. Stained soil at pump jack exhaust.



Photo 3. Combustor lit.

