

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
Good Housekeeping:			
Type	WEEDS		
Comment:	Dead weeds around ancillary equipment		
Corrective Action:	Comply with Rule 606		Date: <u>02/07/2022</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	OTHER		
Comment:	ancillary equip. has fabricated steel pipe		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	hog fence		
Corrective Action:		Date:	
Equipment:			
			corrective date
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead appears inaccessible or not visible		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2)		Date: <u>02/03/2022</u>
Type: Ancillary equipment	# 1		
Comment:	electric panel, meter box and transformers		

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment: <input style="width: 90%;" type="text"/>						Date: _____
Corrective Action: <input style="width: 90%;" type="text"/>						
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
<p>COGCC Inspection Report Summary On Monday 1/24/2022 at approximately 1140 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location: Location: Mahoney 2 API #05-123-09078 County: Weld. While there, I observed a wellsite, PR at the time of inspection During this inspection the following possible compliance issues were observed: 606 houskeeping: Dead Weeds around ancillary equip. CA Date 2-7-2022. 419.a.(1),(2) Bradenhead access: Bradenhead inaccessible or not visible, CA date 2-3-2022. 419.b.(5) Bradenhead Monthly Reporting: bradenhead doesnot appear to be plumbed to surface for testing. Location: some snow and muddy, Weather: clear. A follow up on this site inspection needs to be conducted. Compliance issues appear to have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	revasr	01/24/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402935477	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5642880
699304826	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5642874