

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/31/2022

Submitted Date:

02/02/2022

Document Number:

701102612

FIELD INSPECTION FORM

Loc ID: 324270 Inspector Name: LONGWORTH, MIKE On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 53255
Name of Operator: MARALEX RESOURCES INC
Address: P O BOX 338
City: IGNACIO State: CO Zip: 81137

Findings:

- 8 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Hahn, Travis		thahn@maralexinc.com	All Inspections
Graves, Jim		mrinc20@maralexinc.com	
Byers, Jim		jbyers@blm.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
266869	WELL	SI	09/01/2009	GW	045-09853	SOUTH SHALE RIDGE 1-14H	SI

General Comment:

COGCC Routine Inspection Report Summary
Location is in a High Priority Habitat Area.
During this inspection the following compliance issues were observed:

- Tank label does not meet required information.
- No tank battery sign at tank battery.
- Weeds around well, tank battery, and production equipment.
- Weeds growing inside of tank berm.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	Tank label does not meet required information.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	05/06/2022
Type	BATTERY		
Comment:	No tank battery sign at tank battery.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	05/06/2022
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	_____

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds around well, tank battery, and production equipment.		
Corrective Action:	Comply with 606	Date:	02/19/2022

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:						
Contents	#	Capacity	Type	Tank ID	SE GPS	
			FIBERGLASS AST			
Comment:						
Corrective Action:					Date:	
Paint						
Condition						
Other (Content)	Not posted					
Other (Capacity)	Not posted					
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Insufficient	Inadequate		
Comment:		Weeds growing inside of tank berm.				
Corrective Action:		Maintain berm base and housekeeping.			Date:	02/19/2022
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities

Facility ID: 266869 Type: WELL API Number: 045-09853 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402946519	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5654011
701102620	Inspection 701102612 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5654006