

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/31/2022

Submitted Date:

02/03/2022

Document Number:

701102614**FIELD INSPECTION FORM**Loc ID 312609 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments6 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hahn, Travis		thahn@maralexinc.com	All Inspections
Graves, Jim		mrinc20@maralexinc.com	
, Engineering		dnr_cogccengineering@state.co.us	All engineering
Byers, Jim		jbyers@blm.gov	
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222011	WELL	SI	05/01/2012	GW	077-08613	SOUTH SHALE RIDGE 7-24	SI

General Comment:

COGCC Follow Up Inspection Report Summary

Follow up to 12/07/020 inspection # 699802220

Uncorrected action item(s)

• Last produced April 2010. Last MIT performed on 2/19/15. MIT required.

During this inspection the following compliance issues were observed:

- EMS (911) not posted on battery sign.
- Tank battery sign is illegible and does not meet Rule 605.e.
- Tank label is illegible.
- Weeds around well, production equipment, and tank battery.
- Access road is rutted and lacks stabilization. Road ditch needs maintained.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:	Tank battery sign is illegible and does not meet Rule 605.e.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	05/06/2022
Type	TANK LABELS/PLACARDS		
Comment:	Tank label is illegible.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	05/06/2022
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	EMS (911) not posted on battery sign.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	03/05/2022

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds around well, production equipment, and tank battery.		
Corrective Action:	Comply with Rule 606	Date:	02/20/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Vertical Separator	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
	1		Open Top		,	
Comment:						
Corrective Action:					Date:	

Paint

Condition					
Other (Content)	Not posted				
Other (Capacity)	Not posted				
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 222011 Type: WELL API Number: 077-08613 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: Last produced April 2010. Last MIT performed on 2/19/15.Corrective Action: A mechanical integrity test shall be performed on each shut-in well on 5 year intervals from the date the initial mechanical integrity test was performed. Perform MIT on well. Date: 05/15/2020

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						
		Compaction				
		Ditches				

Comment: [Access road is rutted and lacks stabilization. Road ditch needs maintained.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.\(2\)C](#)

Date: 02/19/2022

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402946521	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5654013
701102622	Inspection 701102614 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5654008